

# BP MC252 INCIDENT DECONTAMINATION & WASTE SITE ASSESSMENT CHECKLIST

Staging Area Designation Cocodrie Waste ID No.(if provided by State) LAR0000170649

Assessment Date: 7/6/2010 Incident Name: Deepwater MC 252

Physical Location: (29.25057 -90.66489) 106 Pier 56

Cocodrie Chauvin LA County: Terrebone Parish  
(City) (State)

Facility Representative/Title: Winston Shero

Facility Representative Phone No.: 201-435-3213

Contractor Representative/Company/Title: John Dillon, Heritage, Project Manager

Contractor Representative Telephone No.: 985-533-6525

Lead Inspector: ERIC NOLD, FOSC

Other Inspectors: Heath Smith, FOSC  
Chris Warn, START

## ASSESSMENT INFORMATION

**Please use the Additional Comments Section below to further explain any Observations of Concern and include photographs**

General Site Information and Observations	
1. Are all BPMC252 wastes being stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Are the rolloff boxes covered when they have been filled (or at the end of the day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Are the containers for contaminated PPE & sorbents in the Decon areas covered except when adding or removing waste?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
4. Was any evidence of spills of oily waste or oily waste waters observed (from rolloff boxes, or under decon pools)? If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A

Additional Comments: During collection of samples from solid waste rolloff box, bags of oily liquid were discovered. Heritage rep. immediately stopped allowing any new bags of waste being added until Heritage and Anderson (company placing the bagged material into the rolloff) could determine a resolution and determine how bagged liquid waste was mistakenly placed in rolloff.

Photographs:

ID	DESCRIPTION
IMG 0726-0756	<u>various photos taken of waste sample collection electronic copies available from Eric Nold EPA OSC. BP tech rep Phillip W/ Enviro. Solutions EN Standards also collected photos</u>

See follow up attachment →

## Attachment

Follow up summary to the Decontamination & Waste Site Assessment Checklist completed 7/6/10

After EPA found liquid oil material in drum liners in the oiled solid waste roll-off box, a Heritage rep immediately stopped allowing any other material from being added and the tarp was placed back over the top and secured. EPA reported to Heritage that at least four other similar bags were noted in the roll-off. A meeting with O'Briens (prime contractor to BP), Heritage, and Anderson was held at the roll-off box area to determine how liquid waste could have been added to this waste-stream.

The initial report back to EPA was that the previous evening, mechanics had been working on a nearby barge and must have changed out oil and placed the waste oil in the roll-off box by mistake (there is a waste-oil waste stream container nearby the roll-off box area). This theory was accepted by EPA as visual staining of the interior of the clear plastic bags was very similar to waste-oil, and not orange/reddish like most of the oil material being recovered from this oil spill.

On the morning of 7/7/10, EPA was informed by the Heritage rep that after a complete investigation of the material in the roll-off box, a total of 20 double wrapped bags of liquid oil material was discovered and many of them had sand within and outside the bags. This revealed that the bags were actually generated during beach cleanup operations from the morning of 7/6/10.

At the morning captains meeting on 7/7/10, O'Briens rep informed all subcontractors conducting cleanup operations that throwing liquid waste into the solid waste roll-off box would not be tolerated. He also informed that when liquid waste was generated, to inform the Heritage rep so that it could be placed in the appropriate waste-stream. The Heritage rep informed them that a Heritage representative and an Anderson Representative would visually inspect every bag prior to entering the roll-off for all future activities, making sure this doesn't happen again. The Heritage rep also informed the EPA rep that if additional liquid waste streams become necessary at the end of the dock (in addition to the current skimmer oil frac tank, oily decon water frac tank, and waste oil drums), proper containers will be added and EPA will be informed.

*Eric J. Gold* EPA OSC  
7/8/10

## BP MC252 INCIDENT DECONTAMINATION & WASTE SITE ASSESSMENT CHECKLIST

Staging Area Designation	Waste ID No.(if provided by State)
--------------------------	------------------------------------

Assessment Date: \_\_\_\_\_ Incident Name: **Deepwater MC 252**

Physical Location: \_\_\_\_\_  
 \_\_\_\_\_ County: \_\_\_\_\_  
 (City) (State)

Facility Representative/Title: \_\_\_\_\_

Facility Representative Phone No.: \_\_\_\_\_

Contractor

Representative/Company/Title: \_\_\_\_\_

Contractor Representative \_\_\_\_\_

Telephone No.: \_\_\_\_\_

Lead Inspector: \_\_\_\_\_

Other Inspectors: \_\_\_\_\_

## ASSESSMENT INFORMATION

**Please use the Additional Comments Section below to further explain any Observations of Concern and include photographs**

General Site Information and Observations	
1. Are all BPMC252 wastes being stored in lined rolloff boxes?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Are the rolloff boxes covered when they have been filled (or at the end of the day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Are the containers for contaminated PPE & sorbents in the Decon areas covered except when adding or removing waste?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
4. Was any evidence of spills of oily waste or oily waste waters observed (from rolloff boxes, or under decon pools)? If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Additional Comments:	
Photographs:	
ID	DESCRIPTION

# BP MC252 INCIDENT DECONTAMINATION & WASTE SITE ASSESSMENT CHECKLIST

Staging Area Designation _____	Waste ID No.(if provided by State) _____
Assessment Date: _____	Incident Name: <b>Deepwater MC 252</b>
Physical Location: _____	_____
(City)	(State)
County: _____	
Facility Representative/Title: _____	
Facility Representative Phone No.: _____	
Contractor Representative/Company/Title: _____	
Contractor Representative Telephone No.: _____	
Lead Inspector: _____	
Other Inspectors: _____	

## ASSESSMENT INFORMATION

**Please use the Additional Comments Section below to further explain any Observations of Concern and include photographs**

General Site Information and Observations	
1. Are all BPMC252 wastes being stored in lined rolloff boxes?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Are the rolloff boxes covered when they have been filled (or at the end of the day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Are the containers for contaminated PPE & sorbents in the Decon areas covered except when adding or removing waste?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
4. Was any evidence of spills of oily waste or oily waste waters observed (from rolloff boxes, or under decon pools)? If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Additional Comments:	
Photographs:	
ID	DESCRIPTION